

ST ANTHONY & OUR LADY OF MERCY RC CHURCH, HULL

REPORT ON VISIBLE DAMAGE TO CHURCH DUE TO WATER INGRESS

Executive Summary:

To be read in conjunction with Garlands roof survey, sketches 1 and 2, photographs pages 1 and 2 and budget cost spreadsheet.

Whilst conducting a roof survey, it was discovered that as well as the roof covering requiring replacing, the reinforced concrete frame was spalling and causing the interior of the church as well as the exterior to degrade.

Repairs to the church can be made and preventative measures taken to delay further deterioration. The costs of doing this (including the roof recovering) will be in the region of £356k. (See attached budget costs.) This cost excludes investigative work and repairs to the main body of the church, as to thoroughly check the portal frames would require complete internal scaffolding and the complete removal of the plaster work surrounding them. There is evidence of one portal frame in an isolated corner suffering corrosion, and an area in the choir loft.

Introduction:

St Anthony & Our Lady of Mercy is situated in the Beverley Road Conservation area of Hull. It was designed by the Architects Williams, Sleight and Company of Hull and opened in 1965. It became a parish in 1976. It is not listed and has not been recommended for listing.

The church is situated to the North of the city centre and sits approximately 0.8 miles away from Our Lady and St Peter Chanel church, 1.8 miles away from St Vincent's church and 2.3 miles away from St Mary Queen of Martyrs Church. Mass attendance figures in 2023 were 182.

The church of St Anthony & Our Lady of Mercy requires re-roofing in its entirety. During the survey on the roof, it was found that there were issues with the reinforced concrete frame and concrete window frames spalling. This led to further investigation into the defects in the structure.

Construction:

The church is fan shaped in plan, with a reinforced concrete wall to the rear which supports all the reinforced concrete portal frames that form the fan shape. The entrance and choir loft are formed from brick walls with decorative concrete clad panelling, a mosaic and a cantilevered canopy. The single storey build to the rear of the church is similarly fashioned and forms the 2 side chapels, the sacristy and meeting room. All the roofs are formed from a reinforced concrete deck with a 25mm thick fibreboard as insulation and either mineral felt or Asphalt roof coverings.

Condition Report:

The building has had a visual survey undertaken to highlight the visible defects. These in turn are shown on the attached location diagrams and photographs and the detailed roof survey report. To undertake a full structural inspection would require full scaffold inside and out and would entail all the plaster ceilings being removed.

The mechanics of spalling concrete are that the concrete is porous and without adequate protection of the steel reinforcing bars within, the steel corrodes. Corrosion entails the steel reinforcing rusting and expanding up to 15 times its original size. This in turn pushes off the concrete cover to the reinforcing therefore allowing more water in and more corrosion. It is clear from the areas of exposed reinforcing that the concrete cover is inadequate; less than the 25mm minimum as required under British Standards for reinforced concrete.

The roof coverings have completely failed. The insulation on the flat roofs (main entrance and rear extension) is saturated, this in turn is allowing water to penetrate the concrete roof deck and corrode the steel reinforcing bars. Evidence of the spalling concrete can be clearly seen on the outside of the structure and by the bowing plasterwork on the undersides of the ceilings within the building, similar to Our Lady Church in Acomb. The bowing plaster ceilings require removal, and the concrete underneath requires repair.

The main support wall has areas of exposed steelwork and evidence of earlier repairs. The loose concrete needs removing, the steel bars treating, repair mortar applied, and a preservative coating applied.

The Bell tower which also acts as a lateral restraint to the main support wall also has exposed reinforcing bars. The loose concrete needs to be removed, the steel bars treated, repair mortar applied, and a preservative coating applied to prevent further corrosion.

The concrete framed windows are spalling and require high build mortar repair.

The underside of the roof overhang around the perimeter of the fan shape has no protective covering and showing signs of failure. There are several large holes at the lower-level joints. The loose concrete requires removal, the steelwork treating, temporary shuttering and high build mortar repairs are required to be followed by a protective coating.

The cantilever canopy has a crack on the underside. This requires repairs and strengthening.

The mosaic is failing, and tiles are missing, this requires stabilising with a clear coating.

The concrete cladding is spalling, this requires the loose concrete removing and a protective coating applying.

Repair Costs:

The estimated repair costs are itemised on the attached spreadsheet and are split into 3 phases:

Phase 1: To prevent further water ingress and further deterioration of the structure £264k


Phase 2: To repair the internal areas that are visibly damaged £46k

Phase 3: To repair the exterior roof overhang, belltower and windows £46k


The costs do not allow for the repairs to the mosaic at the front and assumes that the scaffold for the roof work is re-used for the phase 3 works.

ST ANTHONY & OUR LADY OF MERCY - BUDGET COSTS TO VISIBLE DAMAGE							area m2	rate	cost	VAT	total	Sub Total
PHASE 1: Prevent further water ingress							lot		£ 30,000.00	£ 6,000.00	£ 36,000.00	£ 263,976.00
Scaffold access and edge protection (exterior), include a level to access underside of overhang							lot		£ 500.00	£ 100.00	£ 600.00	
remove redundant water tank							lot		£ 15,000.00	£ 3,000.00	£ 18,000.00	
divert drainage to external hoppers and new downpipes							542	£ 300.00	£ 162,600.00	£ 32,520.00	£ 195,120.00	
strip off existing roof covering and re-roof entire building, to include external insulation							99	£ 70.00	£ 6,930.00	£ 1,386.00	£ 8,316.00	
re-point rear wall							33	£ 150.00	£ 4,950.00	£ 990.00	£ 5,940.00	
concrete repairs to rear wall - magma build and cladding coat												
PHASE 2: repair internal areas showing most damage							lot		£ 1,200.00	£ 240.00	£ 1,440.00	£ 45,840.00
R&D asbestos survey							100		£ 7,500.00	£ 1,500.00	£ 9,000.00	
tower access to low level ceilings, sacristy, side chapels, meeting room etc at church rear							100	£ 50.00	£ 5,000.00	£ 1,000.00	£ 6,000.00	
Remove ceilings (labour plus skip hire) assume all ceilings damaged due to sodden insulation							lot		£ 1,500.00	£ 300.00	£ 1,800.00	
Structural Engineer's inspection fees							100	£ 150.00	£ 15,000.00	£ 3,000.00	£ 18,000.00	
Concrete repairs - Magma build and cladding coat							lot		£ 5,000.00	£ 1,000.00	£ 6,000.00	
redecorate side chapels, sacristy, meeting room etc									£ 3,000.00	£ 600.00	£ 3,600.00	
high level repairs to skylights, lintel above Lady Chapel, high level support rib, choir loft												
PHASE 3: Repair roof perimeter, Bell tower, windows and canopy							100	£ 175.00	£ 17,500.00	£ 3,500.00	£ 21,000.00	£ 45,960.00
note: use scaffold erected for roof repairs							50	£ 150.00	£ 7,500.00	£ 1,500.00	£ 9,000.00	
concrete repairs to roof perimeter - include overhead formers							15	£ 200.00	£ 3,000.00	£ 600.00	£ 3,600.00	
concrete repairs to windows							lot		£ 5,000.00	£ 1,000.00	£ 6,000.00	
repairs and strengthening to cantilever canopy							140	£ 150.00	£ 5,000.00	£ 1,000.00	£ 6,000.00	
additional scaffold to bell tower							lot		£ 300.00	£ 60.00	£ 360.00	
concrete repairs to bell tower												
replace access door to bell tower												
GRAND TOTAL												£ 355,776.00


SKETCH 2



SANCTUARY



ABOVE TABERNACLE



MEETING ROOM



NAVE




LADY CHAPEL



STAIRS



ENTRANCE




CHORUS LOFT




STAIRS





Typical perimeter
antennas



Main structure



Ball tower



Windows

Middlesbrough Diocese Church Buildings



Garland UK

St Anthony's and Our Lady of Mercy Roof Information

Prepared by: David Campos

Prepared for: Sharon Westcough

Date: 04, July, 2024

Table of Contents

Middlesbrough Diocese Church Buildings / Client Data.....3

St Anthonys and Our Lady of Mercy Hull / Facility Summary.....4

St Anthonys and Our Lady of Mercy Hull / Facility Drawing.....5

St Anthonys and Our Lady of Mercy Hull / Roof Areas / Construction Details.....6

St Anthonys and Our Lady of Mercy Hull / Roof Areas / Asset Drawing.....8

St Anthonys and Our Lady of Mercy Hull / Roof Areas / Photo Report: 2 Jul 2024.....9



Client Data

MIDDLESBROUGH DIOCESE CHURCH
BUILDINGS
50A LINTHORPE AVENUE
MIDDLESBROUGH, CLEVELAND TS5 6QT

Client Data

Name	Middlesbrough Diocese Church Buildings		
Address 1	50A Linthorpe Avenue	Address 2	Acklam
City	Middlesbrough	County	Cleveland
Postal	TS5 6QT	Country	United Kingdom



Facility Summary

MIDDLESBROUGH DIOCESE CHURCH
BUILDINGS
50A LINTHORPE AVENUE
MIDDLESBROUGH, CLEVELAND TS5 6QT

FACILITY: St Anthony's and Our Lady of Mercy Hull

Facility Map



Facility Data

Address 1	50A Linthorpe Avenue
Address 2	Acklam
City	Middlesbrough
County	Cleveland
Postal	TS5 6QT
Type of Facility	Religious

Asset Information


Name	Date Installed	Square Meters	Roof Access
Roof Areas	Unknown	610	Ladder Needed

NOTES

1. Contractors to be responsible for checking these notes against architect drawings, site requirements and advise TRS immediately of any discrepancies.
2. This drawing includes sufficient material including any wastages to complete the contract. Any additional material required over and above the quantities shown will be charged to the going rate plus 10% at time of ordering and may also be subject to a transport charge.
3. A full 40% discount shall be given to customers if payment is received in full on delivery.
4. Payment should be made to TRS by bank transfer or cheque.
5. A suitable sized frame to receive edge support to be provided by the customer should be made to all tapered edges of the TRS.
6. All items are cut from whole boards to give the best finish.
7. Fixings will occur within areas of flat surfaces.

ROOF INSULATION LAYOUT

Total Roof Area = 542m²



SCHEMATIC VIEW OF INSULATION (NOT TO SCALE)



THIS IS A CAD GENERATED DRAWING
DO NOT SCALE UNLESS INSTRUCTED.

© Tapered Roofing Systems 2024

REV DATE NOTES
A 14/06/24 INITIAL DRAWING LAYOUT

PLEASE NOTE:

PROVISIONAL SCHEME ONLY.
SUBJECT TO DRAWING APPROVAL
BEFORE SUPPLY.

SCALE 1:50
1:100 @ A1
DATE 14/06/2024
PROJECT ST ANTHONY'S AND OUR LADY OF MERCY
DRAWING NO. GAR 3133J
EFFECTIVE U VALUE 0.16W/MK
CALCULATED IN ACCORDANCE WITH ANNEX C

TRS

TAPERED ROOFING SYSTEMS
Suite B, Unit 15
Severn Farm Enterprise Park
Birmingham
B37 7YU
Tel: 01938 55 22 55
info@taperedroofing.co.uk



Construction Details


MIDDLESBROUGH DIOCESE CHURCH
BUILDINGS
50A LINTHORPE AVENUE
MIDDLESBROUGH, CLEVELAND TS5 6QT

FACILITY: St Anthony's and Our Lady of Mercy Hull

ROOF SECTION: Roof Areas

Asset Map

Asset Photo



Information

Year Installed	Unknown	Square Meters	610
Slope Dimension	Flat < 5°	Eave Height	Approx 9m
Roof Access	Ladder Needed	System Type	Built Up Roof (BUR)




NOTES

1. Contractor to be responsible for checking these details against architect's drawings and requirements and amend TDS accordingly if any discrepancies.
2. This drawing includes sufficient material including any wastages to complete the contract. Any additional material requested over and above the quantities shown will be charged at the going rate (and VAT) at time of delivery and must be subject to a separate charge.
3. A flat and even roof deck surface is assumed. No unevenness is assumed.
4. Loading calculations should be used to bring any unevenness measurements which affect the laying of the scheme up to level.
5. A suitable base material or concrete edge supports (as provided by the contractor) should be fixed to an existing edge of the TDS.
6. TDS will not be fixed unless it is by the contractor.
7. Fixings will cover entire areas of flat surfaces.

ROOF INSULATION LAYOUT

Total Roof Area = 542m²



SCHEMATIC VIEW OF INSULATION (NOT TO SCALE)



THIS IS A CAD GENERATED DRAWING.
DO NOT SCALE UNLESS INSTRUCTED.

© Tapered Roofing Systems 2024

REV DATE NOTES
A 14/06/24 INITIAL DRAWING LAYOUT

PLEASE NOTE:

PROVISIONAL SCHEME ONLY.
SUBJECT TO DRAWING APPROVAL
BEFORE SUPPLY.

SCALE: 1:100 @ A1
DATE: 14/06/2024
PROJECT: ST ANTHONY'S AND OUR LADY OF MERCY

DRAWING NO: GAR 31333
U-VALUE: 0.18 W/M²K
EFFECTIVE U-VALUE: 0.18 W/M²K
CALCULATED IN ACCORDANCE WITH ANNEX C

TRS

TAPERED ROOFING SYSTEMS
Suite 8, Unit 15
Severn Farm Enterprise Park
Worcester
WR21 2EF
Tel: 01905 55 22 55
info@taperedroofing.co.uk



Photo Report

MIDDLESBROUGH DIOCESE CHURCH
BUILDINGS
50A LINTHORPE AVENUE
MIDDLESBROUGH, CLEVELAND TS5 6QT

FACILITY: St Anthony's and Our Lady of Mercy Hull	ROOF SECTION: Roof Areas	TITLE: Condition Report Photos	DATE: 02/07/2024
---	--------------------------	--------------------------------	------------------



Core sample taken revealed fibreboard insulation 25mm R1



Existing parapet capping to be removed and boarded over with plywood




Core sample to R2 showed saturated insulation over concrete deck



Core to gutter area showed no insulation



Gutter section



Existing outlets travel through the building
this should be taken external




R2 Roof Area




Existing parapet to R2



As previous



Poor condition of rooflights



Further example of internal outlet detail where water is travelling through the building

12



Area of moss growth indicating ponding water

13



Further parapet capping to R1

14




Previous repairs have been carried out

15



Visible splits starting to show

16



Glass block glazing will need individual rooflights over the top of the glazing with permanent trickle vents to avoid condensation.

17




Core sample revealed asphalt over concrete deck

18



Poor upstand detail

19



Overview

20



Overview

21



Existing membrane showing signs of mineral loss and deterioration

22




Overview

23




As previous

24




Core sample to lower area R3 showed fibre board over concrete

25



Existing door should either be removed or replaced

26



Water tank (guessing redundant) should be removed

27



Upstand to wall area

28



Evidence of spalling

29




As previous

30




Spalling to vertical section

31



Location




Further image



Existing condition of tower - This could be cladded to encapsulate or treated

34



Further evidence of spalling

35



Poor detailing noted to upstands



Overview showing ponding



Blockage

38




Failed section to parapet

39




Lower sections are in reasonable condition

40



Internal damage

41




As previous

42



Further water ingress damage

43



As previous

44



Water damage

45



External

46



As previous - ideally the outlets should discharge off the end of the roof into hoppers and swan neck to avoid any water passing through the roof